

Zero Fatalities
Zero Lost Time
Zero Road/Speed Incidents
Zero Environmental Incidents
Zero Tolerance of Unsafe Behaviours & Practices



PF Olsen Toolbox Safety Alert 59

Date: June 2023	Focus Group:	Vehicle Drivers
Topic: Black Ice	Issued by:	Nic Steens

Background and Incident: During this recent cold snap a driver has reported sliding on black ice on shaded roads. In past winters, similar incidents have been classified as high potential as they have involved crews of workers and/or multiple vehicles.

Injury Details: No injuries or damage. This toolbox safety alert is precautionary advice.

Risk Awareness: Black ice can cause vehicles to spin 360 degrees or more, and have ineffective braking, which are extreme risk factors for a crash. With NIWA advising above-normal temperatures this winter – frosty periods may catch drivers off guard! Please be alert to (black-ice) conditions and take extreme care!

Safe Behaviours: here are some tips:

- Always pre-check your vehicle for the correct tread depth and tyre pressure.
- Properly de-ice your vehicle before setting off to ensure all-round visibility.
- Leave extra distance/space between you and other road users.
- Keep an eye on vehicles ahead that may suddenly swerve for no apparent reason.
- Avoid over-steering and heavy braking drive slower.
- Black ice forms in sheltered areas without creating bubbles, 'blending' with the road.
- Ice patches average < 6 metres if you lose traction, stay calm and don't brake. If
 you start going off the road, steer the vehicle gently to the safest place.
- If you crash, quickly evaluate whether it is safer to stay in your car or to get out of it.

For Site Manager:	
Print and complete the following:	
1. Discuss with employees/operators:	
2. Place on-site notice board or in file:	
Site Manager: Date: / /	
(initials)	